

APPLICATION : Food industry


LOCATION : France

DIFFICULTY : Elongation

CHAIN TYPE : Stainless steel

# CUSTOMER SUCCESS

An industrial manufacturer of dried fruit used to install standard stainless steel 12B-2 duplex roller chains on their fruit washing machine. But the **elongation** of stainless steel was so important that the chain had to be replaced on average every 6 months, what created **recurrent maintenance costs** (maintenance team workforce, repeated purchase price of the chains, production stops costs...).



By replacing the European competitor's standard chain by a **high resistance Alpha Premium STAINLESS STEEL chain** for an almost equivalent price, the service life on the installation has been improved significantly. Thanks to the treated stainless steel with increased surface hardness, the **resistance against wear and the breaking load have improved** considerably. The customer has installed the new chain more than one year ago and has still not replaced it !



CHAIN SERVICE LIFE  
**MULTIPLIED BY 2**



SAVINGS  
ON MAINTENANCE



REDUCTION OF  
PRODUCTION SHUTDOWNS

CHAIN SERVICE LIFE  
**x2 minimum**  
compared to the competitor's chain